



GENERAL INFORMATION

ASE200 is an aerosol self etching primer designed to promote adhesion and improve corrosion resistance over a variety of metal substrates. Recommended for sand throughs and small areas.



1. COMPONENTS

- ASE200



2. MIXING RATIO

Ready to use.



3. POT LIFE @ 77°F (25°C)

Indefinite



4. CLEAN UP

To clean nozzle: Invert can and spray for about 3 seconds.



5. ADDITIVES

N/A



6. SURFACE PREPARATION

- Remove all dirt, grease, wax and rust.
- Clean with 170
- Sand and featheredge all areas to be primed with 320 grit sandpaper.
- Clean surface with 155 Surface Cleaner or 170 and wipe dry with clean cloth before product flashes.



7. SUBSTRATES

- Steel
- Aluminum
- Most types of galvanized steel



8. APPLICATION

Shake can for 2 minutes and repeat for 10 seconds after each minute of use. Apply 2 to 3 thin coats. Dry mils 0.2 to 0.4 mils.

* Surface temperature should be 60-90°F (16-32°C)



9. FLASH / DRY TIMES

To topcoat 20 minutes

May be lightly sanded after 30 minutes.



10. PHYSICAL DATA

Volume Solids	13.9%
Weight Solids	6.7%
MIR Value	1.02 g ozone/gram
Recommended DFT	0.2 - 0.4 mils

NOTES

The data on this sheet represent typical values. Since application variables are a major factor in product performance, this information should serve only as a general guide. Valspar assumes no obligation or liability for use of this information. **UNLESS VALSPAR AGREES OTHERWISE IN WRITING, VALSPAR MAKES NO WARRANTIES, EXPRESS OR IMPLIED, AND DISCLAIMS ALL IMPLIED WARRANTIES INCLUDING WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR FREEDOM FROM PATENT INFRINGEMENT. VALSPAR WILL NOT BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES.** Your only remedy for any defect in this product is the replacement of the defective product, or a refund of its purchase price, at our option.